




L100 Firmware Update Steps for Windows

Note: When using for the first time, you'll need to extract the downloaded "L100 firmware update.zip" file to Windows using an extraction tool. You'll also need a USB-A to USB-C or USB-C to USB-C cable that supports data transfer to connect to your Windows computer.

Firmware update steps

Steps 1


Connect the L100's charging port to a USB-C or USB-A data port on your computer using a USB-C to C or USB-A to C data cable:



Steps 2


Open the "L100 upgrade tool" folder and launch the "L100 upgrade tool-Windows.exe" application.

L100 upgrade tool-Windows.exe



Steps 3

Click the "Open" button in the tool and select the firmware file.




Steps 4

Locate the extracted upgrade tool folder, then select the firmware file "L100-Firmware" with the .hex extension from the L100 Firmware folder.

L100-Firmware.hex

Steps 5

Once selected, click the "Burn" button and wait for the latest firmware to be written.



Steps 6

Wait until the upgrade tool displays "CRC Verification successful," which means the firmware update is complete.

